



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
January 18, 2007

Supervisor ADZ

Mine Name: Rocky Point

Operator Name: Orton Ranch & Development, Inc

Permit number: M0030042

Inspection Date: January 10, 2007

Time: 10:30 am

Inspector(s): Lynn Kunzler and Daron Haddock, DOGM

Other Participants: JD Marriott

Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine inspection while in the area.

Inspection Summary:

1. There has been no activity at this site for several months. In July of 2006, this site was sold to Marriott Construction, however a permit transfer was never filed. We reviewed the permit requirements with the new owner and left a transfer form for him to complete. It was also pointed out that the annual permit fee was not paid and needs to be remitted ASAP.

On Wednesday, January 17, 2007, Randy Marriott hand delivered the completed transfer form and a check for the permit fee.

Conclusions and Recommendations:

1. Continue to monitor this site when in the area.

Inspector's Signature

Date: January 18, 2007

LK:pb

O:\M003-BoxElder\S0030042-Rockypoint\inspections\insp-01102007.doc